

Project Name: Gold King Mine – September 11, 2014	Site Location: Silverton, San Juan County, Colorado	Project No. NA
---	---	--------------------------



Photo No. 1	Date: 09/11/2014	
Direction Photo Taken: North		
Description: Gold King Mine prior to 2014 site work. Photo taken on 9/11/2014 at 12:37 pm prior to start of work. 3-inch Parshall flume is at the right of the photo, in the plastic structure.		

Photo No. 2	Date: 09/11/2014	
Direction Photo Taken: East		
Description: Gold King Mine prior to 2014 site work. Photo taken on 9/11/2014 at 12:38 pm prior to start of work. Low flow in discharge channel.		



Project Name: Gold King Mine – September 11, 2014	Site Location: Silverton, San Juan County, Colorado	Project No. NA
---	---	--------------------------





Photo No. 3	Date: 09/11/2014	
Direction Photo Taken: South		
Description: Gold King Mine 3-inch Parshall flume. Note low flow in channel. Photo taken on 9/11/2014 at 12:42 prior to the start of work. Water is at 0.1 feet, which corresponds to 12.55 gallons per minute flow.		

Photo No. 4	Date: 09/11/2014	
Direction Photo Taken: South		
Description: Gold King Mine 3-inch Parshall flume. Note low flow in channel. Photo taken on 9/11/2014 at 12:43 prior to the start of work. Water is at 0.1 feet, which corresponds to 12.55 gallons per minute flow.		

Project Name: Gold King Mine – September 11, 2014	Site Location: Silverton, San Juan County, Colorado	Project No. NA
---	---	--------------------------

Photo No. 5	Date: 09/11/2014	
Direction Photo Taken: Northwest		
Description: Small amount of flow from side adit approximately 100 feet west of main adit/flume. Photo taken on 9/11/2014 at 12:53.		
Photo No. 6	Date: 09/11/2014	
Direction Photo Taken: Northwest		
Description: Start of 2014 excavation work. Photo taken on 9/11/2014 at 15:10.		